

# THE OFG COOPERATIVE GROUP HOUSING SOCIETY LTD.

Sector-9, Plot No. 50, Rohini, Delhi-110085

'Oriental Apartment'

---

11/12/2018


Dear Residents,

**Re.: Repair/renovation of Overhead Water Tank of your Block**

It has been reported to us by the plumber of the Society and even some of the Block Residents that the condition of the Overhead Water Tank is in a very bad shape and is leaking at places which needs immediate repair. You are all aware that as per the decision of the General Body Meeting the renovation, repair work of the Overhead Water Tank is to be taken care of by the Block Residents only. Any laxity/negligence on the part of any block flat owner can lead to heavy losses of property or human life. We have already suffered a lot because of the carelessness of one flat owner for which we were forced to contribute as compensation to the aggrieved party. We therefore sincerely request all the flat owners of the block to please join hands and get the repair/renovation of Overhead Water Tank immediately before it is too late to mend. Your immediate action in the matter may seal any chances of any type of loss. We are sure and confident that the flat owners will take immediate action to avoid any eventuality.

With regards,

Thanking you,



President / Secretary